Wednesday, 12/5/2007 12:55:56 PM Kim Johnston **Process Sheet** : FLOAT SKIDTUBE **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 35740 : 10366 Estimate Number : D412742013 **Part Number** P.O. Number : 12/5/2007 S.O. No. : **Drawing Number** · N/A This Issue : N/A : NC Project Number Prsht Rev. : N/A : LANDING GEAR : // **Drawing Revision** First Issue Type : 35745 Material Previous Run Each **Due Date** : 12/30/2007 Qty: 1 Um: Written By Checked & Approved By 05.10.13 New Issue KJ/JLM Comment 06-06-08 As per DSI9336 JLM Est Rev:B ECN 1072 DD verified by:JLM Est RevC 07-12-03 **Additional Product** Job Number: Machine Or Operation: Description: Seq. #: DOCUMENT CONTROL 1.0 DC Comment: DOCUMENT CONTROL Der ECNILOY 11 08-04-14) Photocopy bluefile and create labels per PPP D412-742-013 FLOAT SKID ASSEMBLY 2.0 35740A Comment: Sub-Component FLOAT SKID ASSEMBLY D412-742-043 B 35740A PACKAGING RESOURCE #1 3.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Pick Packing Kit D2571 4.0 Saddle, Fwd, Out Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: Description **Qty Part Number** Batch 1 D2571 Saddle Fwd Outside D2572 5.0 Saddle, Fwd, In Comment: Qty.: 1.0000 Each(s)/Unit 1.0000 Each(s) Total: Pick: **Qty Part Number** Description 1 D2572 Saddle Fwd Inside


Dart Aerospace Ltd	U
--------------------	---

W/O:			W	ORK ORDER CHAN	GES	· , ,	-		
DATE	STEP	PRO	CEDURE CHA	NGE		Ву	Date Qt	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•						
Part No	: <u> </u>	PAR #:	Fault Cate	gory:	NCR	: Yes N	lo DQA: _	Date: _	
			100V 000					Date: _	
NCR:		V		ER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	ction B	Sign & Date	Verification C		Approval QC Inspector
	-								

Wednesday, 12/5/2007 12:55:56 PM Kim Johnston Ĵser: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 35740 Part Number: D412742013 Job Number: Description: Seq. #: Machine Or Operation: D2573 Saddle, Aft, Out 6.0 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: Pick: Qty Part Number Description Batch 1 D2573 Saddle Aft Outside Saddle, Aft, In D2574 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: Pick: Description **Qty Part Number** Batch 1 D2574 Saddle Aft Outside D2876 ment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Description Qty Part Number Saddle Spacer 2 D2876 D2877 9.0 Saddle Spacer 2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: Pick: Qty Part Number Description 2 D2877 Saddle Spacer D34031 Comment: Qty.: 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Pick: **Qty Part Number** Description 16 D3403-1 Bushing D2747 11.0 Set Screw Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) **Qty Part Number** Description 4 D2747 Bolt


Dart	Aeros	pace	Ltd
------	-------	------	-----

Dart Ae	rospace Lt	td											
W/O:		WORK ORDER CHANGES											
DATE	STEP	STEP PROCEDURE CHANGE						Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect			
–––– Part No	:	PAR #:	Fault Cate	gory:	NCI	R: Yes	No DQ	A:	Date:				
						QA: N	C Close	d:	_ Date: _	····			
NCR:			WORK ORD	ER NON-CONFO	RMANCE	(NCR)						
DATE	STEP	STEP Description of NC Section A		Corrective Action Section Initial Action Description		Sign &	Verific Secti	cation on C	Approval Chief Eng	Approval QC Inspecto			
			Chief Eng	Chief Eng		Date							
								;	i				




Dart Aero	space	Ltd
-----------	-------	-----

Dart Ae	rospace	Ltd							
W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·									
Part No	•	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	_ Date: _	
					QA:	N/C Close	d:	_ Date: _	
NCR:			WORK ORDI	R NON-CONFORMA	NCE (NC	R)			*
	STED Description of NC			on B	Verific	cation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	Approval QC Inspector
							•	i	




Dart Aerospace Ltd	Dart A	Aeros	pace	Ltd
---------------------------	--------	-------	------	-----

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	DCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				•								
			· · · · · · · · · · · · · · · · · · ·									
Part No	•	PAR #:	Fault Cate	gory:	NC	R: Yes	No DQ	\ :	Date:			
									Date:	,		
NCR:			WORK ORD	ER NON-CONFOR	MANCE	(NCR)					
DATE	STEP	Description of NC	Corrective Action Section B			Verification			Approval	Approval		
DATE	SIEF	Section A	Initial Chief Eng	Action Descriptio Chief Eng	on'	Sign & Date	Section		Chief Eng	QC Inspector		
w.												
		·								·		
					-							
							:					
										,		
							1			1		



Dart Aerospace	Ltd
-----------------------	-----

		- 									
W /O:			WORK ORDER CHANGES								
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cate	jory:	NCR	: Yes	No DQA	\ :	Date:		
						QA: N	/C Closed	l:	_ Date: _		
NCR:			WORK ORDE	ER NON-CONFORM	MANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section B			verification A			Approval	Approval	
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	n	Sign & Date	Section	on C	Chief Eng	QC Inspector	
							·				
					-						
		·									
										,	



Dart Ae	rospace L1	td							
W/O:	1		W	ORK ORDER CHANGES	<u> </u>			Annewal	
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
						······································			
Part No	:	PAR #:	Fault Cat	egory: N	CR: Yes	(6) DO	A: <u>\</u>	Date: <u>△</u>	81818
					QA: N	V/C Close	ed:	Date: _	
NCR:			WORK ORE	DER NON-CONFORMANC	E (NCF	₹)			
DATE		Description of NC		Corrective Action Section B			cation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	on Sign & Date		tion C	Chief Eng	QC Inspect

Date: Wednesday, 12/5/2007 12:55:56 PM Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 35740 Part Number: D412742013 dob Number: Description: Seq. #: **Machine Or Operation:** PACKAGING RESOURCE #1 PACKAGING 1 40.0 Identify and pack for shipping as per PPP D412-742-013 Location: FINAL INSPECTION/W/O RELEASE 41.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE - 200F/3/12 Job Completion

Dart Ae	rospace L	td // / ~)	93,94,75,					
W/O:		•	WC	ORK ORDER CHANGE	S			
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	
					QA: N	/C Closed:	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (NCR)		
DATE	STEP	Description of NC	<u> </u>	Corrective Action Section		Verification	Approval	Approva
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
							•	

Qty:

Each

1 Um:

: FLOAT SKID ASSEMBLY

: D412742043

D3391 REV G

: 12/30/2007

: N/A

: 🗺

Date

Wednesday, 12/5/2007 12:56:11 PM

User

Kim Johnston

Process Sheet

Drawing Name

Part Number

Material

Due Date

KJ/JLM

JLM

EC

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

S.O. No. :

: 35740A : 10756 **Estimate Number**

P.O. Number

: 12/5/2007 This Issue

: NC Prsht Rev.

First Issue Previous Run : //

: 35745A

Written By Checked & Approved By

Comment

: Est Rev A 05.10.13

Type

Est Rev B '06.02.13

Est Rev:C 07-05-28 Est Rev:D 07-12-04

by:JLM

New Issue

ECN 773 dwg @ rev.D

ECN 1072

: LANDING GEAR

As per Rev F

DD verified

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

If D412-742-043 is a W/O on it's own,

Photocopy bluefile and create labels per PPP D412-742-043 CHG003

2.0


HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391 **BK** 08-03-07 A/R LPS-3 **M** 105005



2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment, using 7/16" "T" Pins.

Expiry date:

Expiry date:

Sikaflex-241/-291 M 165 285

Bel 08-03-07

3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon".

Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex.

08-03-07

A/R LPS Procyon

A/R

Sikaflex-241/-291 105585 08-07

BR 08-03-07

4-Remove "T" pins once sikaflex is dry.

5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser.

Page 1

W/O:			W	ORK ORDER CHANG	SES					
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:					
							QA: N/C Closed:			
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE	(NCR)	1			
DATE	STEP	Description of NC	Corrective Action Section B			Verification		ation	Approval	Approval
DAIL		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
								1		
					i.					

Wednesday, 12/5/2007 12:56:11 PM Date: Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 35740A Part Number: D412742043 Job Number: Seq. #: **Machine Or Operation:** Description: D3391023 Mid Tube Assembly 3.0 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: pick: Qty Part Number Description D3391-023 Mid Tube Assembly D3391025 4.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Qty Part Number Description D3391-025 Aft Tube Assembly 08-03-07 5.0 D35641 **WEARSHOE** Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) WEARS 6.0 D35661 **GASKET** Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) **GASKET** 7.0 D35643 WEARSHOE Comment: Qty.: 1.0000 Each(s)/Unit 1.0000 Each(s) _Total: **WEARSHOE** 8.0 WEARSHOE Comment: Qty.: Each(s)/Unit Total: 1.0000 Each(s) WEARSHOE K 9.0 D35665 GASKET Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) **GASKET** Batch:

Page 2

W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	(No) DQ	A: <u>\butacktrianger</u> :A	Date: <u>_</u>	108/03/19			
					QA: N	I/C Close	d:	_ Date: _				
NCR:		V	ORK ORDI	ER NON-CONFORMA	NCE (NCF	₹)						
DATE	STEP	Description of NC	Corrective Action Section B			Verific	cation	Approval	Approval			
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Sect	Section C	Chief Eng	QC Inspector			
		·										
								<u>-</u>				

Wednesday, 12/5/2007 12:56:12 PM Date: User: Kim Johnston **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 35740A Part Number: D412742043 Job Number: Description: Seq. #: Machine Or Operation: 10.0 AN3C4A Comment: Qty.: 24.0000 Each(s) Total: **BOLT** Batch: AN3C6A 11.0 Comment: Qty.: Total: 12.0000 Each(s) **BOLT** Batch: 12.0 AN3C7A Comment: Qty.: Total: 8.0000 Each(s) **BOLT** Batch: 13.0 Comment: Qty.: 44.0000 Each(s)/Unit Total: 44.0000 Each(s) washer 14.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 15.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-043 Location: PPP Rev: 16.0 Comment: FINAL IN mi 2008/3/12 Job Completion

Dart Aerospace L

W/O:		WORK ORDER CHANGES								
DATE	STEP	PR	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
:										
Part No:		PAR #:	Fault Category: NO			s No DQ	A:	Date:		
								Date: _		
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NO	CR)				
DATE	STEP	Description of NC	Corrective Action Section B			Verification		Approval	Approval	
	Section A		Initial Action Descrip Chief Eng Chief Eng		Sig: Da	1&t _{Sect}	tion C	Chief Eng	QC Inspector	
								£ .		

